Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight — ***DHR Id#:*** **046-5092**

Resource Identification

Property Name(s): ..... Fox Run {Current}
Property Date: ..... ca 1890
Address(s): ..... 24519 Buckhorn Road {Current}
Route 610 {Alternate}
County/Independent City: Isle Of Wight
City: ..... Windsor
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR
UTM Coordinates: 18/4073977/0344207
Surrounding area: ..... Town

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Interior	Asphalt	Chimneys - Corbeled Cap
Foundation	Foundation - Solid	Concrete	Foundation - Block
Porch	Porch - 1-story, 3-bay	Wood	Porch - Victorian
Roof	Roof - Gable, Side	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Vinyl Siding
Windows	Windows - Sash	Metal	Windows - 1/1
Windows	Windows - Sash, double-hung	Wood	Windows - 2/2

Site Description: ..... This farmstead is located immediately outside the Windsor town limits on the southwest side of town. The farm is located on the east side of the road.

Secondary Resource Desc: Outbuildings are located east and south of the dwelling.

WUZIT Count:

No.	Wuzit Types	Historic?
1	Single Dwelling	Historic
1	Kitchen	Historic
1	Equipment Shed	Non-historic
1	Shed	Historic
1	Barn	Historic
2	Silo	Non-historic

NR Resource Count:

#	NR Resource Type	Contributing Status
4	Building	Contributing
2	Structure	Non-contributing
1	Building	Non-contributing

Contributing: 4.00 Non-Contributing: 3.00 Total: 7.00

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5092**

Individual Resource Information

WUZIT: ..... Silo

Est. Date of Construction: .... 1960 post {Site Visit}
Accessed? ..... No
Primary Resource? ..... No
Number of Stories: 0.0
Interior Plan Type: .....
Threats to Resource: ..... Transportation Expansion

Description: Two small, round, metal silos are located between the barn and the road.

WUZIT: ..... Barn

Est. Date of Construction: .... 1950 ca {Site Visit}
Accessed? ..... No
Primary Resource? ..... No
Number of Stories: 0.0
Interior Plan Type: .....
Threats to Resource: ..... Transportation Expansion

Description: 2This two-level barn is covered by a standing seam gable roof with shed extensions on the east and west sides. The barn is clad with horizontal board siding and is set on a foundation of brick piers and concrete blocks. Sliding doors on the north, west, and east sides give access to the stalls on the lower level. Two shed-roofed additions, constructed on the south end of the barn, are clad with T-111 siding. Barn doors on the west side of the shed additions open to the stalls inside. Two small, round, metal silos are located between the barn and the road.

WUZIT: ..... Shed

Est. Date of Construction: .... 1950 {Site Visit}
Accessed? ..... No
Primary Resource? ..... No
Number of Stories: 1.0
Interior Plan Type: .....
Threats to Resource: ..... Transportation Expansion

Description: This one-story, frame shed is covered by a gable roof of 5-V crimp metal, and is clad with horizontal board siding. Double-leaf, swinging doors are located on the west end of the shed. A door is located on the south side. The shed's use was undetermined.

WUZIT: ..... Equipment Shed

Est. Date of Construction: .... 1980 ca {Site Visit}
Accessed? ..... No
Primary Resource? ..... No
Number of Stories: 1.0
Interior Plan Type: .....
Threats to Resource: ..... Transportation Expansion

Description: This one-story, concrete block machine shed, located southeast behind the house, is covered with a gable roof of 5-V crimp metal with horizontal board siding in the gable ends. A sliding door on the west side opens into the large equipment storage space on the north end of the shed; an enclosed office area is located on the south end and is accessed by a door on the west side of the building.

WUZIT: ..... Kitchen

Est. Date of Construction: .... 1900 ca {Site Visit}
Accessed? ..... No
Primary Resource? ..... No
Number of Stories: 1.0
Interior Plan Type: .....
Threats to Resource: ..... Transportation Expansion

Description: This one-story frame building, located east behind the house, may have been a kitchen wing that was attached to the rear of the house. It is covered by a front-facing, metal-clad gable roof, is clad with weatherboard, and has a door on the west end. A brick chimney is located on the east end of the building, and six-over-six wood sash windows are located on the north and south sides. The kitchen is set on brick piers. A shed-roofed addition that holds two horse stalls is located on the east end. The stalls are clad with horizontal and vertical board siding.

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-5092**

WUZIT: ..... Single Dwelling

Est. Date of Construction:	1890 ca {Site Visit}	*Accessed?*	No
Primary Resource?	Yes	*Number of Stories:*	2.0
Architectural Style:	Late 19th and Early 20th Century A	*Condition:*	Fair
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: This two-story, three-bay, frame I-house is covered by a side-facing gable roof of standing seam metal with a front gable wall dormer that features shaped wooden shingles and decorative scrollwork brackets. The house is clad with vinyl siding, which covers the house's foundation. The one-story, three-bay front porch is covered by a hipped roof that is supported by wooden Doric columns. Fixed and sliding glass doors have been installed between the columns, enclosing the front porch. The centrally located entrance has a three-light transom above and two-pane sidelights. The entrance is flanked by two-over-two wood sash windows. Brick chimneys are located near the north and south ends of the roof ridge. Other details include decorative cornice brackets, shaped shingles in the gable ends, and gable end returns.

A one-story, gable-roofed ell has been constructed to the rear (east) of the house. The ell is set on a foundation of concrete block, is clad with vinyl siding, and has wooden decks located on the north, south, and east sides.

Cemetery Information

Bridge Information

National Register Eligibility Information *(Intensive Level Survey)*

Historic Time Period(s):..... P- Reconstruction and Growth (1865 to 1914)

Significance Statement: This late-nineteenth century, Victorian-style I-house is typical of others found in the region and in the nearby town of Windsor. Although exhibiting Victorian-era detailing in the use of shaped shingles and scrollwork, material changes have been made to the house including the installation of vinyl siding and the enclosing of the front porch. The outbuildings, likewise, are of common design, construction, and materials. The resource has no apparent association with any event or person important in our nation's history and does not appear to have the ability to yield important information. For these reasons, the resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Ownership Information

Name: ..... Unknown Keeling

Zip: ..... *State:* *Country:*

Relation to the Property: Owner of property

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	7	VDHR	2004/07/22	Single Dwelling, Roll 34

Cultural Resource Management (CRM) Events

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5092**

CRM Event # 1,

Cultural Resource Management Event:	Phase I Survey
Date:	2004/08/31
Organization or Person:	CCR, Inc.
VDHR Project ID # Associated with Event: ..	2002-1760
CRM Event Notes or Comments:	VDHR # 2002-1760 VDOT # 0460-969-101, PE-101 Architectural Survey, Route 460 Alternative #1 Corridor Study

CRM Event # 2,

Cultural Resource Management Event:	DHR Staff: Not Eligible
Date:	2004/11/18
Organization or Person:	
VDHR Project ID # Associated with Event: ..	2002-1760
CRM Event Notes or Comments:	